

SECRET

0140009-0
PRIORITY 1

1967 NOV 17 22 032

OUT63621

25X9 E C R E T 172153Z CITE [REDACTED] 2277

25X PRIORITY

172153Z

CITE

2277

1. CAMERA B-24 WAS USED ON MISSION G994 FLOWN 16 NOVEMBER 1967.
PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE AND RESOLUTION WERE GOOD THROUGHOUT FOR BOTH SIDES.

B. 9R SIDE: SLIGHT INBOARD ROLLER CHATTER IS PRESENT INTERMITTENTLY THROUGHOUT. THE POSITION INDICATORS ARE SHARP; HOWEVER, THEY ARE UNDEREXPOSED. A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 133 AND HEAT SPLICES OCCUR IN FRAME 882 AND BETWEEN FRAMES 1821 AND 1822.

C. 9L SIDE: POSITION INDICATORS ARE READABLE; HOWEVER, THEY APPEAR UNDEREXPOSED. THE DATA BLOCK IS OVEREXPOSED, NOT SHARPLY IMAGED, AND IS DIFFICULT TO READ. THERE IS A MANUFACTURER'S SPLICING IN FRAMES 661 AND 1115. HEAT SPLICES ARE PRESENT IN FRAMES 12, 72, AND 861.

D. BOTH SIDES: ROLLER CHATTER AND EDGE STATIC IS VERY MINOR AND CAUSE NO IMAGE DEGRADATION. FRAME 1920 IS THE LAST TITLED FRAME ON BOTH THE 9L AND 9R SIDES.

3. POSITIVES:

A. PRINTING AND PROCESSING ARE GOOD.

B. PI SUITABILITY IS GOOD THROUGHOUT.

C. CLOUDS OBSCURE APPROXIMATELY 35 PERCENT OF THE MISSION.

GP- 1

~~SECRET~~

END OF MESSAGE

DISTRIBUTION		
By No.	Office	Action
2	FILE	
US		
	SEC BR	
	TOS	
	OSB	
	PSD	
	PD	
	PSD	
	CSB-ICB	
	TCD	
	WAB	
	PSD	
	UNAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

NGA review(s) completed.

SECRET

